



Motorcycles

Tourist, Sportsman, Ranger



Spare parts catalogue

Edition 2018

Fig. EFI 01.01




Fig. EFI 01.02




Fig. EFI 01.03




Fig. EFI 01.04




Fig. EFI 01.05




Fig. EFI 01.06




Fig. EFI 01.07




Fig. EFI 01.08





Fig. EFI 01.09



Rocker LeftHand



Rocker RightHand




Fig. EFI 01.10




Fig. EFI 03.01



Fig. EFI 03.02




Fig. EFI 04.01




Fig. EFI 04.02




Fig. EFI 04.03




Fig. EFI 04.04




Fig. EFI 04.05




Fig. EFI 05.01




Fig. EFI 05.02




Fig. EFI 05.03




Fig. EFI 05.04




Fig. EFI 05.05




Fig. EFI 05.06



Fig. EFI 05.07




Fig. EFI 06.01




Fig. EFI 06.02




Fig. EFI 06.03



Fig. EFI 07.01



Fig. EFI 07.02




Fig. EFI 07.03



Fig. EFI 08.01



Ural-“T” :




Fig. EFI 08.02




Fig. EFI 08.03




Fig. EFI 09.01




Fig. EFI 09.02




Fig. EFI 09.03




Fig. EFI 09.04




Fig. EFI 09.05




Fig. EFI 10.01




Fig. EFI 10.02



URAL 1

2WD 2

WARNING!
LEFT AND RIGHT HAND TURNS MAY BE
DANGEROUS WITH SIDECAR ACCESSORY.
AVOID EXCESSIVE SPEED. WHEN
STOPPED SET PARKING BRAKE.
READ THE OWNER'S MANUAL

3

Fig. EFI 10.03




Fig. EFI 11.01




Fig. EFI 11.02





Fig. EFI 11.03



Until 2016



From 2017




Fig. EFI 11.04




Fig. EFI 12.01



Fig. EFI 13.01




Fig. EFI 13.02 Front seat 2017



Fig. EFI 13.03 Front Seat 2/3



Fig. EFI 14.01




Fig. EFI 14.02 Rear seat 2017



2



Fig. EFI 15.01




Fig. EFI 15.02




Fig. EFI 16.01





Fig. EFI 16.02



Fig. EFI 16.03



3



3



Fig. EFI 16.04




Fig. EFI 16.05




Fig. EFI 16.06




Fig. EFI 16.07




Fig. EFI 16.08



Fig. EFI 17.01




Fig. EFI 17.02




Fig. EFI 17.03




Fig. EFI 18.01




Fig. EFI 18.02




Fig. EFI 18.03




Fig. EFI 18.04



Fig. EFI 18.05




Fig. EFI 19.01




Fig. EFI 19.02




Fig. EFI 20.01




Fig. EFI 20.02




Fig. EFI 20.03




Fig. EFI 20.04




Fig. EFI 20.05




Fig. EFI 20.06





Fig. EFI 20.07



23



Fig. EFI 20.08





Fig. EFI 21.01




Fig. EFI 21.02




Fig. EFI 21.03




Fig. EFI 24.01



Fig. EFI 26.01




Fig. EFI 26.02




Fig. EFI 26.03




Fig. EFI 27.01



Fig. EFI 27.02




Fig. EFI 27.03

